

## Troubleshooting Guide for Quadrants

### **DOOR NOT ALIGNING**

1. Is the tray 100% level?
2. Have the walls been checked at different levels to ensure consistency?
3. Are the wall profiles stepped in 15mm from the edge of the tray?
4. Do the finished tile measurements on the tray comply with the adjustment listed on the label and in the specifications book?
5. Have the wall profiles been adjusted in or out to ensure door closes properly?
6. Are the rollers properly adjusted?
7. Is the top rail level?
8. Door is touching the back wall when open – product needs to be adjusted correctly.
9. Door not closing properly on the closing upright seal – product needs to be adjusted correctly.
10. Moving panel seal rubbing off the curved fixed panel – product needs to be adjusted correctly.

### **DOOR LEAKING**

1. Is the bottom seal fitted on the glass panel?
2. Are the upright seals fitted?
3. Is the door sealed correctly?

### **OTHERS**

1. Door is hitting the bottom of the glider - adjust rollers to raise door).
2. Opening space is too small – need to reduce the roller stop length.
3. Bottom moving panel seal 10S10AP570 is hard to assemble – put in warm water for a few minutes to soften and then assemble.
4. Rubbing/scratching noise when door is being opened and closed – locating pin is not adjusted. Must be in centre of slot on the top rail